

### Continuous Radon Monitor

Model Number: 1028  
Calibration Date: 04/30/2008  
Monitor Time: 2/24/2009 11:11

Serial Number: 49745012  
CF: 2.86

### Inspector Information

Martin Newmark  
Abacus Inspection Service  
248 S Madison Ave  
Louisville  
CO-80027  
Phone Number: 303-554-5840  
License Number: 103889RT

### Customer Information

Jane Doe  
1234 Any Street  
Louisville, CO


### Site & Condition

Monitor Location: Main floor

### Test Summary

Start Time: 02/20/2009 13:14  
End Time: 02/22/2009 13:14  
Measurement Interval(hr): 1.0  
Elapse Time: 2 Days 0 hrs

EPA Avg: 7.5 pCi/l



\*\*\*\*\* 02/20/2009 \*\*\*\*\*

Time	Counts pCi/l	Flags
14:14	4.2	
15:14	6.6	
16:14	5.2	M
17:14	7.7	
18:14	5.9	
19:14	3.8	
20:14	3.5	
21:14	7.3	
22:14	5.9	
23:14	8.4	

\*\*\*\*\* 02/21/2009 \*\*\*\*\*

Time	Counts pCi/l	Flags
00:14	7.0	
01:14	8.7	
02:14	9.8	
03:14	6.3	
04:14	7.3	
05:14	7.0	
06:14	4.2	
07:14	4.9	
08:14	7.3	
09:14	6.6	
10:14	5.6	
11:14	7.0	
12:14	5.9	
13:14	8.0	
14:14	7.7	
15:14	5.2	
16:14	5.9	
17:14	6.3	
18:14	8.4	
19:14	9.1	
20:14	6.3	
21:14	9.8	
22:14	8.4	
23:14	8.4	

\*\*\*\*\* 02/22/2009 \*\*\*\*\*

Time	Counts pCi/l	Flags
00:14	5.6	
01:14	10.5	
02:14	7.7	
03:14	10.8	

\*\*\*\*\* 02/22/2009 \*\*\*\*\*

Time	Counts pCi/l	Flags
04:14	9.4	
05:14	7.7	
06:14	8.4	
07:14	7.3	
08:14	9.1	
09:14	8.4	
10:14	6.3	
11:14	5.9	
12:14	8.0	
13:14	8.7	

Error Flags:

M Motion:



PC Software Version: 2.1.1.0

Embedded Software Version: 105